Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: PEOPLES GAS LIGHT AND COKE CO.	Operator ID#: 15329
Inspection Date(s): 5/28/2015, 5/29/2015	Man Days: 2
Inspection Unit: South Shop	
Location of Audit: Chicago	
Exit Meeting Contact:	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Kevin Hecker	
Company Representative to Receive Report: Amy Kenny, Tom Webb	
Company Representative's Email Address: ALKenny@peoplesgasdelivery.com, TJWebb@peoples	sgasdelivery.com

CONSTRUCTION INFORMATION			
Location of Construction:		Construction P	erformed By:
South LaFayette Avenue between 102nd a	and 103rd Streets.	K&S Construction	n, contracted by Peoples Gas
Contractor Foreman:	The K&S foreman for this	project was Mike	Parrelli.
Operator Inspector:	The K&S inspector for this project was Andre Anderson.		
Person(s) On Job Site			
	<u> </u>	•	

Description of Construction:

Staff observed the boring of a new 2" PE main as part of the Peoples Gas AMRP along South LaFayette Avenue between 102nd and 103rd Streets.

MAIN INSTALLATION		Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.5]	Class location :	Class 4
[192.619,192.621,192.623]	MAOP	25 psig
[192.63]	Pipe Size :	2"
[192.55,192.59]	Specification :	ASTM D2513

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.55,192.59]	Manufacturer :	Driscoplex
[192.55,192.59]	Pipe Grade :	PE2406/2708
[192.55,192.59]	Wall Thickness :	DR 11
[192.63(a)(2)]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
General Comment:		
All pipe observed contained the required markings. No	valves or fitting were observed during this installation.	
[192.227]	Date of Welder qualification:	Not Applicable
General Comment:		
No steel pipe is being used for this project.		
[192.227]	Welder's Name:	Not Applicable
General Comment:		
No steel pipe is being used for this project.		
[192.225,192.275,192.277,192.279,192.283]	Is pipe joined in accordance with approved written procedures?	Not Checked
General Comment:		
No plastic joining was observed during this audit.		
[192.285]	Date of Plastic Joining Qualification :	Not Checked
General Comment:		
No plastic joining was observed during this audit.		
[192.285]	Joiner's name:	Not Checked
General Comment:		
No plastic joining was observed during this audit.		
[192.455]	Is buried metallic pipe coated?	Not Applicable
General Comment:		
No steel pipe is being used for this project.		
[192.461]	Does coating meet 192.461?	Not Applicable
General Comment:		
No steel pipe is being used for this project.		
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
General Comment:		
No steel pipe is being used for this project.		
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	Not Applicable

PEOPLES GAS LIGHT AND COKE CO./5-29-2015

Page 2 of 5

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
No steel pipe is being used for this project.		
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	Not Applicable
General Comment:		
No steel pipe is being used for this project.		
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:		
No steel pipe is being used for this project.		
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
No steel pipe is being used for this project.		
[192.479]	Are above ground facilities cleaned and coated or jacketed as needed?	Not Applicable
General Comment:		
No above ground facilities were installed during this audi	it.	
[192.303]	Are comprehensive written construction specifications available and adhered to?	Satisfactory
[192.305]	Are inspections performed by the operator to check adherence to the construction specifications?	Satisfactory
[192.307]	Is material being visually inspected at the site of installation to ensure against damage that could impair its serviceability?	Satisfactory
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Not Checked
General Comment:		
Staff concluded the audit prior to any backfilling.		
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
[192.321(e)]	Does plastic pipe have means of locating while underground?	Satisfactory
[192.325]	Are required clearances from underground structures being maintained?	Satisfactory
[192.327]	Is required cover being obtained appropriate to type of pipeline and location?	Satisfactory
General Comment:		
Staff observed a depth of 36-42" during the boring proce	ess. Depth was also checked at the pot holes near each service tee by the inspec	ctor.
[192.503]	Are general testing requirements being met?	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
Staff did not observed pressure testing during	ng this audit.	
[192.517]	Are records being made of strength and leak tests?	Not Checked
General Comment:	·	
Staff did not observed pressure testing during	ng this audit.	
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
[192.805(c)]	Were non-qualified personnel being directed and observed by a qualified individual?	Not Applicable
General Comment:		
Staff did not observe any non-qualified pers	onnel during this audit. All personnel observed were qualified for the tasks performed.	
[192.805(c)]	Were span of control limitations being followed?	Not Applicable
General Comment:	·	
Staff did not observe any non-qualified pers	connel during this audit. All personnel observed were qualified for the tasks performed.	
Was a Protocol 9 (Form 15) Compl	eted?	No
[192.614]	Were One Call Notifications performed as required?	Satisfactory
[192.614]	Dig Ticket #	564025697
[192.751]	Are adequate steps taken to minimize the potential for accidental ignition?	Satisfactory
General Comment:		
A fire extinguisher was located near the pot	holes during boring.	
[192.719(b)]	Was each repair made by welding to a transmission line made in accordance with 192.713, 192.715, and 192.717 and examined in accordance with 192.241?	Not Applicable
General Comment:		
No transmission pipe was observed as part	of this audit.	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.